



Firmware for OnCell G4308-LTE4 Series Release Notes

Version: v3.18.0	Build: 25062612
Release Date: Aug 07, 2025	

Applicable Products

OnCell G4308-LTE4 Series

Supported Operating Systems

N/A

New Features

- Added Traceroute CLI command.
- Introduced multi-language support for MX-ROS, including Traditional/Simplified Chinese, Korean, and Japanese.
- Added GRE interface on Network Interface.
- Added OSPF support to Routing.
- Added serial interface support for integration with ITS SCATS systems.
- Added support for MRC Quick Link Ultra v4.1.0.
- Added support for displaying the cellular carrier in MRC Quick Link Ultra.
- Added support for MRC-related logs in the system log.

Enhancements

- Added support for "Route Mode" in IPsec Startup Mode. In Route Mode, the VPN tunnel initiates only when routing packets are generated, relying on traffic to trigger the tunnel.
- Added support for CLI commands to configure MXsecurity port settings.
- The "Ping Response" function has been moved from the "User Interface" (MX-ROS v3.12.1 to v3.13) and "Trusted Access" (MX-ROS v3.6) pages to the dedicated "Ping Response" page.
- Added IP display on the Querier Connected Port in the IGMP Snooping Group Table.
- Added Passive Mode to OSPF.
- Added Object types: Secure FTP and SYSLOG (TCP 514) to Object Management.
- Added trap and syslog support for IPS/DPI/ADP to Advanced Protection - Configuration.
- Optimized IPsec reconnection time.
- Reduced the data usage of the MRC service when monitoring the status of devices.

Bugs Fixed

- When exporting the configuration, the Object IP Range setting is saved incorrectly, causing importing the configuration to fail.
- MXview 1.4.1 does not receive encrypted SNMPv3 Trap/Inform packets from the routers.
- ARP Reply packets are being unintentionally dropped in Bridge mode.
- Email Settings cannot be disabled.
- After changing the Management VLAN, the router is unreachable when pinged.
- When configuring Bridge members, the system unintentionally creates two untagged VLANs under the access port.
- Multicast traffic is not filtered correctly, causing forwarding to ports that have not joined the IGMP group.
- IPsec Startup Mode - Initiate Automatically does not function properly.
- CVE-2024-9138, CVE-2024-9140 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-241155.
- CVE-2025-0415 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-259491.
- CVE-2025-0676 vulnerability issue(s). For more details, search the Security Advisories section on



the Moxa website for the following Security Advisory ID: MPSA-251431.

Changes

- Supervisor and user accounts are no longer created by default, and must be added manually. Existing accounts are not affected.
- In compliance with the EU Radio Equipment Directive (RED), users must change the password on first login.

Notes

- Due to an issue, using an identical pre-shared key to set up multiple site-to-any IPsec VPN tunnels with IKEv1 mode requires a workaround. Please contact Moxa Technical Support for assistance.
- Using an MRC Gateway key with a different gateway model may cause connection issues with the MRC service.