



## Firmware for SDS-3000, SDS-G3000 Series Release Notes

<b>Version: v3.2</b>	<b>Build: 25042315</b>
<b>Release Date: May 23, 2025</b>	

### Applicable Products

N/A

### Supported Operating Systems

N/A

### New Features

- Added the MECHATROLINK-4 configuration option to the web interface and DIP switch.

### Enhancements

- Added support for the standard MRP MIB library.

### Bugs Fixed

- [CVE-2025-1680] An open redirect vulnerability occurs when an application allows a user to control a redirect or forward to another URL.

### Changes

N/A

### Notes

- Upgrading firmware from v2.2 or earlier to v3.0 or later will reset the management VLAN to its default value (VLAN 1). Other VLAN settings are not affected. If you upgraded the firmware under the aforementioned conditions, please use VLAN 1 to access the switch and reconfigure the relevant settings. Contact your local Moxa Technical Support team if you need further assistance.



<b>Version: v3.1</b>	<b>Build: 25022018</b>
<b>Release Date: Mar 18, 2025</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

N/A

### **Bugs Fixed**

- [CVE-2024-7695] An out-of-bounds write vulnerability caused by insufficient input validation allows attackers to overwrite memory beyond the buffer's bounds.
- [CVE-2024-9404] Due to insufficient input validation, exploitation of the moxa\_cmd service could lead to denial-of-service or service crashes.
- [CVE-2024-9137] Attackers could execute specified commands to perform unauthorized downloads or uploads of configuration files and compromise the system.
- [CVE-2024-12297] Frontend authorization logic disclosure vulnerability.
- After rebooting the switch, the system name is deleted in PROFINET applications.
- The switch cannot be accessed through the management VLAN with certain VLAN configurations.

### **Changes**

N/A

### **Notes**

- Upgrading firmware from v2.2 or earlier to v3.0 or later will reset the management VLAN to its default value (VLAN 1). Other VLAN settings are not affected. If you upgraded the firmware under the aforementioned conditions, please use VLAN 1 to access the switch and reconfigure the relevant settings. Contact your local Moxa Technical Support team if you need further assistance.



<b>Version: v3.0</b>	<b>Build: 24070920</b>
<b>Release Date: Sep 30, 2024</b>	

### **Applicable Products**

SDS-3006 Series, SDS-3008 Series, SDS-3010 Series, SDS-3016 Series, SDS-G3006 Series, SDS-G3008 Series, SDS-G3010 Series, SDS-G3016 Series

### **Supported Operating Systems**

N/A

### **New Features**

- Added support for the Trusted Access function.
- Added support for the Fiber Check function.
- Added support for Smart PoE features.

### **Enhancements**

- For security reasons, the Modbus/TCP protocol is now disabled by default.
- Supports TLS v1.3.

### **Bugs Fixed**

- [CVE-2015-9251] jQuery versions prior to v3.0.0 may be vulnerable to Cross-site Scripting attacks.
- [CVE-2019-11358] jQuery versions prior to v3.4.0 mishandle jQuery.extend because of Object.prototype pollution.
- [CVE-2020-11022] [CVE-2020-11023] jQuery versions later than v1.2 and prior to v3.5.0 may execute untrusted code when passing HTML from untrusted sources.

### **Changes**

N/A

### **Notes**

- Upgrading firmware from v2.2 or earlier to v3.0 or later will reset the management VLAN to its default value (VLAN 1). Other VLAN settings are not affected. If you upgraded the firmware under the aforementioned conditions, please use VLAN 1 to access the switch and reconfigure the relevant settings. Contact your local Moxa Technical Support team if you need further assistance.



<b>Version: v2.2</b>	<b>Build: N/A</b>
<b>Release Date: Sep 08, 2023</b>	

### **Applicable Products**

SDS-3008 Series, SDS-3016 Series

### **Supported Operating Systems**

N/A

### **New Features**

- Added support for the MRP Manager function.

### **Enhancements**

- The SNMP protocol is now disabled by default to improve security.

### **Bugs Fixed**

- Users are unable to enable or disable ports through EtherNet IP.
- The MRP status cannot be displayed after importing a GSD file.
- Importing a GSD file will show an error in the TIA portal.
- [CVE-2022-40691] A specially crafted HTTP request can lead to disclosure of sensitive information.
- [CVE-2022-40224] A specially-crafted HTTP message header can lead to denial of service.

### **Changes**

- Removed the recommended browser notice from the web interface.

### **Notes**

N/A



<b>Version: v2.1</b>	<b>Build: FWR_SDS3000_V2.</b>
<b>Release Date: May 06, 2021</b>	

**Applicable Products**

SDS-3016 Series, SDS-3008 Series

**Supported Operating Systems**

N/A

**New Features**

- Adds support for MXview v3.2.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A



<b>Version: v2.0</b>	<b>Build: N/A</b>
<b>Release Date: Mar 31, 2021</b>	

### **Applicable Products**

SDS-3016 Series, SDS-3008 Series

### **Supported Operating Systems**

N/A

### **New Features**

- Add SDS-3016 Series.
- Web-based GUI for port diagnostics with statistics to detect and prevent issues.
- Supports MRP client redundancy based on IEC 62439-2 to ensure high network availability.
- IP port binding to ensure critical devices can be replaced quickly without reassigning the IP Address.
- Add QoS/DSCP for data priority.
- Static port lock to enhance network security.

### **Enhancements**

N/A

### **Bugs Fixed**

N/A

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.2</b>	<b>Build: FWR_SDS3008_V1.</b>
<b>Release Date: Jan 31, 2020</b>	

## **Applicable Products**

SDS-3008 Series

## **Supported Operating Systems**

N/A

## **New Features**

N/A

## **Enhancements**

- [MSRV-2017-011][CVE-2019-6561] Supports browser cookie parameters “same-site” to eliminate CSRF attacks.

## **Bugs Fixed**

- Login issue with Chrome v65.
- The system rebooted when SNMP GET with request ID=0.
- Log in issue after a new user was created in the multi-language webpage.
- [MSRV-2017-006][CVE-2019-6557] Buffer overflow vulnerabilities that may have allowed remote control.
- [MSRV-2017-007][CVE-2019-6522] An attacker could read device memory on arbitrary addresses.
- [MSRV-2017-009][CVE-2019-6565] No proper validation of user inputs, which allows users to perform XSS attacks.
- [MSRV-2017-011][CVE-2019-6561] CSRF attacks were possible if browser cookie parameters were not correct.
- [MSRV-2017-012][CWE-121] A stack-based buffer overflow condition whereby the buffer that was being overwritten was allocated on the stack.

## **Changes**

N/A

## **Notes**

- MSRV is Moxa's internal security vulnerability tracking ID.



<b>Version: v1.1</b>	<b>Build: Build_17060809</b>
<b>Release Date: Aug 03, 2017</b>	

**Applicable Products**

SDS-3008, SDS-3008-T

**Supported Operating Systems**

N/A

**New Features**

- Multi-language web GUI: English, Traditional Chinese, Simplified Chinese, Japanese, German, and French.

**Enhancements**

- Optimize web page loading performance.

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A





<b>Version: v1.0</b>	<b>Build: Build_16122620</b>
<b>Release Date: N/A</b>	

**Applicable Products**

SDS-3008, SDS-3008-T

**Supported Operating Systems**

N/A

**New Features**

- First release.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A