

Firmware for EDR-8010 Series Release Notes

Version: v3.28	Build: 26070918
Release Date: Jul 16, 2026	

Applicable Products

EDR-8010 Series

Supported Operating Systems

N/A

New Features

- Added 802.1ad VLAN mode.
- Added VXLAN support.
- Added 2-Factor Authentication.
- Added High Availability redundancy protocol.
- Added LDAP support.
- Supports multicast routing without changing TTL using CLI commands.
 - "ip mroute udp-ttl-nochange" (Do not decrement the TTL of UDP multicast routed packets).
 - "no ip mroute udp-ttl-nochange" (Decrement the TTL of UDP multicast routed packets [default]).
 - "show ip mroute udp-ttl-nochange" (Display the current TTL no-change setting).

Enhancements

- Add EAP-TLS and PEAP-MSCHAPv2 support for 802.1X Local Authentication Security.
- Added interface option to Trusted Access settings.
- Added granular DoS protection based on destination IP and service port, with configurable thresholds and action modes.
- Added custom threshold configuration and alarm notifications for fiber port TX/RX and temperature to Fiber Check.
- Support restricting primary/secondary/tertiary DNS servers from being set to the same IP address.
- S7comm DPI now converts difficult protocol codes into clear, user-friendly operation names.
- OPC UA provides predefined OPC UA profiles and objects that group required service codes by common operations.
- Added optional Strict Protection mode to DPI-EIP/CIP.

Bugs Fixed

- MXsecurity fails to backup/restore configuration.
- The configurable System Time year range is different between the Web and CLI.
- Incorrect DHCP pool exhaustion event log may be generated.
- IPS licenses cannot be applied through MXsecurity in some conditions.
- Unexpected Ping Response rules may generate when importing a configuration without Ping Response settings.
- Abnormal OSPF with GRE interface.
- Incorrect user-facing text on session expiration dialog title and button.
- Intermittent failure of SFP fiber link.

Changes

- USB /ABC-02 function now enabled by default.

Notes

- CLI usage instructions for multicast routing without changing TTL.



- ip mroute udp-ttl-nochange
Mode: Global Configuration (config)#
- no ip mroute udp-ttl-nochange
Mode: Global Configuration (config)#
- show ip mroute udp-ttl-nochange
Mode: Privileged EXEC #



Version: v3.24.13	Build: 26061114
Release Date: Jun 17, 2026	

Applicable Products

EDR-8010 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- When a bridge interface and NAT N-to-1 are enabled and simultaneously in use in the same environment, connecting a computer to the bridge port causes abnormal router behavior.
- Directed forwarding does not work after a reboot.
- MXsecurity fails to backup/restore configuration.

Changes

N/A

Notes

N/A



Version: v3.24	Build: 26041517
Release Date: Apr 18, 2026	

Applicable Products

EDR-8010 Series

Supported Operating Systems

N/A

New Features

- Added relay control actions for firewall events.
- Added support for establishing IPsec connections using domain names.

Enhancements

- RSA key supports 3072- and 4096-bit key length for Certificate Signing Request function.
- The login message supports comma characters.
- The System Event Summary supports displaying the number of events in the last 24 hours.
- VLAN/LAN number expansion.
- Object Management supports FTP Passive mode.
- Supports creating SNMP accounts.
- Supports Object Grouping.
- Supports identification of embedded CIP command type (Service Code) in EIP traffic.

Bugs Fixed

- Intermittent ping loss during link-down events.
- TACACS does not work when using FW v3.21 and later.
- MAC-table VLAN sorting non-functional.
- SNMPv3 fails after importing the configuration.
- FTP communication fails using LF newline characters.
- CVE-2026-3867 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-261521.
- CVE-2026-3868 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-261521.

Changes

- IPsec supports LAN interface connections.

Notes

N/A

Version: v3.23	Build: 25123121
Release Date: Jan 09, 2026	

Applicable Products

EDR-8010 Series

Supported Operating Systems

N/A

New Features

- Added Directed Forwarding.
- Added RX Discard.
- Added Neighbor MAC Change events.
- Added Connection Management.

Enhancements

- SNMP/SNMP Trap supports SHA-256 and SHA-512 authentication.
- Port Usage Alarm supports SNMP Trap.
- Tech Support File allows users to generate and import files for troubleshooting.
- Ping tool supports selecting source interface.
- WAN Redundancy feature supports configuring domain names as ping hosts for each interface.
- Supports identification of embedded CIP command type (Service Code) in EIP traffic.

Bugs Fixed

- An error occurs when viewing LLDP entries through the web interface or via SSH.
- Link-up failure after device reboot.
- Turbo Chain fails after importing the configuration file to the head.
- Failed to import configuration file.
- CPU usage reaches 100% after uploading security package v13.0.28.
- SNMP v3 traffic is blocked, causing devices to be SNMP-unreachable in MXview One.
- Page freezes when Asset Recognition is enabled.
- Trap information for MAC address table changes is incorrect.
- Using the wizard to configure all ports to bridge mode deletes VLAN 1.
- Cannot get up-to-date SNMP OID values through SNMP.
- Unexpected Turbo Ring v2 topology changes.
- Web interface not accessible via HTTP after HTTPS is disabled.
- System time incorrect after importing configuration. (Fixed in v3.21.0)
- OpenVPN client configurations occasionally fail to import.

Changes

- When relay activates, the STATE LED also triggers.

Notes

N/A



Version: v3.22	Build: 25102916
Release Date: Nov 11, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Added a CIP Service Code option to the EtherNet/IP (EIP) Protocol Filter Object.

Bugs Fixed

- Port Trunking does not work properly.

Changes

N/A

Notes

N/A



Version: v3.21	Build: 25100115
Release Date: Oct 03, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added mechanism to detect syslog server availability.
- Added a notification feature for soon-to-expire licenses.

Enhancements

- Expanded the number of bridge zones to eight sets.

Bugs Fixed

- WAN interface IP address abnormality after reboot in NAT 1-to-1 mode.
- CVE-2025-6892, CVE-2025-6893, CVE-2025-6894, CVE-2025-6949, CVE-2025-6950 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-258121.
- System time was incorrect after importing configuration.

Changes

- Changed the behavior of user account password modification.

Notes

N/A



Version: v3.20	Build: 25082113
Release Date: Aug 27, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- IPS function disabled after upgrading the firmware.

Changes

N/A

Notes

N/A



Version: v3.19	Build: N/A
Release Date: Jul 31, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added SMTPS support in email settings.
- Added support for LACP protocol.
- Added Domain Protection.
- Added Asset Recognition.

Enhancements

N/A

Bugs Fixed

- Unexpected space characters in IPsec VPN Tunnel name settings.
- The local time does not change according to the selected time zone when Daylight Saving Time is enabled.
- State LED UI hint not accurate.
- Navigating to Syslog page causes unexpected sign out.
- Device stops responding to NTP requests from LAN clients.
- Certain characters in passwords cause sign in failures.
- Enabling or disabling a user account required re-entering the password modification.

Changes

- Simplified license management and IPS licensing.

Notes

N/A



Version: v3.17	Build: 25032717
Release Date: Apr 02, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added Traceroute CLI command.
- Introduced multi-language support for MX-ROS, including Traditional/Simplified Chinese, Korean, and Japanese.
- Added GRE interface on Network Interface.

Enhancements

- Extended Multi-WAN support to accommodate up to 4 WAN connections.
- Added Object types: Secure FTP and SYSLOG (TCP 514) to Object Management.
- Added Offline IDS mode to IPS.
- Added trap and syslog support for IPS/DPI/ADP to Advanced Protection - Configuration.
- Optimized IPsec reconnection time.

Bugs Fixed

- Bridge topology change packets are not properly bypassed, causing increased Turbo Chain recovery time.
- Web UI fails to disable SFP, leaving link status active.
- Multicast traffic is not filtered correctly, causing forwarding to ports that have not joined the IGMP group.
- IPsec Startup Mode - Initiate Automatically does not function properly.
- “Log Service Ready Log Handler” repeatedly reports messages after enabling notification in System log.
- CVE-2025-0415 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-259491.
- CVE-2025-0676 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-251431.

Changes

- Supervisor and user accounts are no longer created by default, and must be added manually. Existing accounts are not affected.

Notes

Small amounts of packet loss may occur when two identical EDR-8010 devices are connected via Static Routes. Instead of using a Static Route, configure the route as a Gateway from WAN settings.

Version: v3.14	Build: 24123112
Release Date: Dec 31, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Added support for "Route Mode" in IPsec Startup Mode. In Route Mode, the VPN tunnel initiates only when routing packets are generated, relying on traffic to trigger the tunnel.
- Added support for CLI commands to configure MXsecurity port settings.
- The "Ping Response" function has been moved from the "User Interface" (MX-ROS v3.12.1 to v3.13) and "Trusted Access" (MX-ROS v3.6) pages to the dedicated "Ping Response" page.
- Added IP display on the Querier Connected Port in the IGMP Snooping Group Table.

Bugs Fixed

- Routed traffic is not correctly processed according to the configured QoS rules.
- MXview 1.4.1 does not receive encrypted SNMPv3 Trap/Inform packets from the routers.
- ARP Reply packets are being unintentionally dropped in Bridge mode.
- Email Settings cannot be disabled.
- After changing the Management VLAN, the router is unreachable when pinged.
- When configuring Bridge members, the system unintentionally creates two untagged VLANs under the access port.
- CVE-2024-9138, CVE-2024-9140 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-241155.

Changes

- Changed the QoS DSCP Mapping table to start from 0x0(0) instead of 0x0(1).

Notes

Due to an issue, using an identical pre-shared key to set up multiple site-to-any IPsec VPN tunnels with IKEv1 mode requires a workaround. Please contact Moxa Technical Support for assistance.



Version: v3.13.1	Build: 24111415
Release Date: Nov 18, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- ARP Reply packets are incorrectly dropped in Bridge Mode.
- When exporting the configuration, the Object IP Range setting is saved incorrectly, causing importing the configuration to fail.

Changes

N/A

Notes

N/A

Version: v3.13	Build: 24100800
Release Date: Oct 09, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added a CPU usage notification to Event Notification.
- Added a port usage notification to Event Notification.
- Added support for new DPI protocols to Advanced Protection: Step7 Comm+, OPC UA, MELSEC.
- Added support for RFC 5424 formatted syslog messages.
- Added a Default Action Log to Layer 3-7 Policy.

Enhancements

- Added Syslog as a Registered Action for the VRRP State Changes event notification.
- Added syslog as a Registered Action for the Fiber Check Warnings event notification.
- Error logs for failed configuration imports now show more details.
- Users can now select multiple inbound interfaces for Static Multicast Routes within same group address.
- Added error logs for the DHCP function.
- Added error logs for the IGMP function.
- Added support for Modbus DPI protocols in the CLI.

Bugs Fixed

- The port-based DHCP server incorrectly assigns duplicate IP addresses to bridge ports.
- RSTP incorrectly assigns multiple devices as the root.
- Users are only able to configure or import one Static Multicast entry through the CLI.
- SNMP OIDs including the "newline" character returns an error.
- Importing configurations containing SNTP/NTP server or SNTP client settings results in an error.
- The NAT function does not work properly after rebooting the device.
- The PRP traffic function for MTU configuration does not work properly.
- The firewall pop-up window remains visible after the system automatically logs out.
- IEEE 802.1X authentication for the RADIUS server would fail.
- Vulnerability: CVE-2024-9137
- Vulnerability: CVE-2024-9139
- Vulnerability: CVE-2024-1086
- The connection status of the OpenVPN Client function shows incorrectly.

Changes

- Increased the maximum password and share key length to 64 characters for user accounts, IPsec, L2TP server, SNMP, IEEE 802.1X, RADIUS server, and TACACS+ server.
- Added support for special characters in passwords and shared keys for user accounts, IPsec, L2TP server, SNMP, IEEE 802.1X, RADIUS server, and TACACS+ server.

Notes

N/A



Version: v3.12.1	Build: 24082116
Release Date: Aug 26, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Unsupported or unavailable features appear in the web interface.

Changes

N/A

Notes

N/A



Version: v3.12	Build: 24073101
Release Date: Aug 02, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added support for the Loopback Interface function.
- Added support for the OpenVPN Client function.
- Added support for the Netflow function.
- Added support for event-triggered actions to the VRRP function.
- Added support for UDP-Flood to the DoS Policy function.
- Added SNMP Trap as a Log Destination for the Layer 2 Policy function.
- Added support for additional event log export formats: .pdf, .csv.

Enhancements

- Enhanced the following IPsec algorithms.
 - Encryption: AES-256-GCM
 - Hash: SHA-512
 - DH Group: DH15 (modp3072), DH16 (modp4096), DH17 (modp6144), DH18 (modp8192), DH22 (modp1024s160), DH23 (modp2048s224), DH24 (modp2048s256), DH31 (curve25519)
 - PRF: PRF SHA-256, PRF SHA-384, PRF SHA-512

Bugs Fixed

- The maximum supported number of tunnels shown at the bottom of the IPsec Settings page is incorrect.
- The "Login Authentication Failure Message" does not save properly.
- Using the newline character (\n) in the 'Login Message' and 'Login Authentication Failure Message' causes abnormalities in the output.
- The system is unable to ping the VRRP virtual IP.
- Users are able to bypass password policy violation warnings by pressing ESC on the keyboard.
- Time zone settings are not saved if GMT is set to 0.
- Vulnerability: CVE-2024-6387.

Changes

- Changed the IPS license expiration behavior: When the license expires, IPS functionality will now remain enabled, but the IPS patterns will no longer be updated.
- Changed the Trusted Access behavior: Trusted Access now applies to the Web UI, CLI, and New Moxa Command interfaces.
- Changed the Preempt Delay range for the VRRP function from 10 to 300 to 0 to 300.

Notes

N/A



Version: v3.6	Build: 24032802
Release Date: Apr 03, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added Turbo Chain support for Layer 2 Redundancy.

Enhancements

- Modified the DoS policy for Flood Protection to allow independent limit ranges for each interface.

Bugs Fixed

- Restoring the device configuration may fail under specific circumstances.
- The allowed characters for the Password Policy are shown incorrectly.

Changes

N/A

Notes

N/A



Version: v3.3	Build: 24010416
Release Date: Jan 12, 2024	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added support for TACACS+ authentication.
- Added Port Disable ingress action for Rate Limit function.
- Added support for LAN ID to DHCP option 82 in the DHCP relay agent.
- Added support for Proxy ARP for LAN interfaces.

Enhancements

- Increased the maximum username length to 32 characters for local account, SNMP, RADIUS, and IEEE 802.1X authentication.
- Increased the maximum length length of passwords, communities, and shared keys to 64 characters for local account, SNMP, RADIUS, and IEEE 802.1X authentication.
- Unified the range of supported special characters for local account, SNMP, RADIUS, and IEEE 802.1X.

Bugs Fixed

- The STATE LED behaves abnormally when no event notifications have been triggered.
- Users are unable to access the web console if their login passwords includes "\$\$".
- Units are incorrectly displaying as "packets" on the vertical axis of network statistics.
- Network statistics values are inaccurate when using ports for measurement.

Changes

N/A

Notes

N/A



Version: v3.1	Build: 23090419
Release Date: Sep 20, 2023	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A