



Firmware for OnCell G4302-LTE4 Series Release Notes

| | |
|-----------------------------------|------------------------|
| Version: v3.23.0 | Build: 25123121 |
| Release Date: Jan 09, 2026 | |

Applicable Products

OnCell G4302-LTE4 Series

Supported Operating Systems

N/A

New Features

- Added SMTPS support in email settings.
- Added RIP routing protocol support.
- Added mechanism to detect syslog server availability.
- Added Neighbor MAC Change events.
- Added Connection Management.

Enhancements

- Added a CIP Service Code option to the EtherNet/IP (EIP) Protocol Filter Object.
- Expanded the number of bridge zones to eight sets.
- SNMP/SNMP Trap supports SHA-256 and SHA-512 authentication.
- Tech Support File allows users to generate and import files for troubleshooting.
- Ping tool supports selecting source interface.
- WAN Redundancy feature supports configuring domain names as ping hosts for each interface.
- Supports identification of embedded CIP command type (Service Code) in EIP traffic.

Bugs Fixed

- An error occurs when viewing LLDP entries through the web interface or via SSH.
- Link-up failure after device reboot.
- Failed to import configuration file.
- SNMP v3 traffic is blocked, causing devices to be SNMP-unreachable in MXview One.
- Trap information for MAC address table changes is incorrect.
- Cannot get up-to-date SNMP OID values through SNMP.
- Web interface not accessible via HTTP after HTTPS is disabled.
- System time incorrect after importing configuration.
- OpenVPN client configurations occasionally fail to import.
- Enabling GRE over IPsec sometimes causes packet loss.
- System logs frequently report unnecessary switching between Cellular WAN and 12.12. Ethernet WAN when WAN Redundancy was enabled.
- Cellular Internet indicator occasionally red despite a successful connection.
- Incoming voice calls to device SIM number cause cellular data connection to drop.
- CVE-2025-6892, CVE-2025-6893, CVE-2025-6894, CVE-2025-6949, CVE-2025-6950 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-258121.

Changes

- Changed the behavior of user account password modification.
- When relay activates, the STATE LED also triggers.
- Cellular Diagnostics function now under "Cellular Debugging" in Diagnostic Support menu.

Notes



N/A

| | |
|-----------------------------------|------------------------|
| Version: v3.18.0 | Build: 25062612 |
| Release Date: Jul 31, 2025 | |

Applicable Products

OnCell G4302-LTE4 Series

Supported Operating Systems

N/A

New Features

Added Traceroute CLI command.

Introduced multi-language support for MX-ROS, including Traditional/Simplified Chinese, Korean, and Japanese.

Added GRE interface on Network Interface.

Added OSPF support to Routing.

Added serial interface support for integration with ITS SCATS systems.

Added support for MRC Quick Link Ultra v4.1.0.

Enhancements

Added support for "Route Mode" in IPsec Startup Mode. In Route Mode, the VPN tunnel initiates only when routing packets are generated, relying on traffic to trigger the tunnel.

Added support for CLI commands to configure MXsecurity port settings.

The "Ping Response" function has been moved from the "User Interface" (MX-ROS v3.12.1 to v3.13) and "Trusted Access" (MX-ROS v3.6) pages to the dedicated "Ping Response" page.

Added IP display on the Querier Connected Port in the IGMP Snooping Group Table.

Added Passive Mode to OSPF.

Added Object types: Secure FTP and SYSLOG (TCP 514) to Object Management.

Added trap and syslog support for IPS/DPI/ADP to Advanced Protection - Configuration.

Optimized IPsec reconnection time.

Bugs Fixed

When exporting the configuration, the Object IP Range setting is saved incorrectly, causing importing the configuration to fail.

MXview 1.4.1 does not receive encrypted SNMPv3 Trap/Inform packets from the routers.

ARP Reply packets are being unintentionally dropped in Bridge mode.

Email Settings cannot be disabled.

After changing the Management VLAN, the router is unreachable when pinged.

When configuring Bridge members, the system unintentionally creates two untagged VLANs under the access port.

Multicast traffic is not filtered correctly, causing forwarding to ports that have not joined the IGMP group.

IPsec Startup Mode - Initiate Automatically does not function properly.

CVE-2024-9138, CVE-2024-9140 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-241155.

CVE-2025-0415 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-259491.

CVE-2025-0676 vulnerability issue(s). For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-251431.

Changes

Supervisor and user accounts are no longer created by default, and must be added manually.

Existing accounts are not affected.

In compliance with the EU Radio Equipment Directive (RED), users must change the password on



first login.

Notes

Due to an issue, using an identical pre-shared key to set up multiple site-to-any IPsec VPN tunnels with IKEv1 mode requires a workaround. Please contact Moxa Technical Support for assistance. Using an MRC Gateway key with a different gateway model may cause connection issues with the MRC service.

| | |
|-----------------------------------|------------------------|
| Version: v3.13.0 | Build: 24100800 |
| Release Date: Oct 08, 2024 | |

Applicable Products

OnCell G4302-LTE4 Series

Supported Operating Systems

N/A

New Features

- Added support for the Loopback Interface function.
- Added support for event-triggered actions to the VRRP function.
- Added support for UDP-Flood to the DoS Policy function.
- Added SNMP Trap as a Log Destination for the Layer 2 Policy function.
- Added support for additional event log export formats: .pdf, .csv.
- Added a CPU usage threshold alarm to the Event Notifications function.
- Added a port usage threshold alarm to the Event Notifications function.
- Added support for Step7 Comm+, OPC UA, and MELSEC to the Advanced Protection function.

Enhancements

- Enhanced the following IPsec algorithms.

Encryption: AES-256-GCM

Hash: SHA-512

DH Group: DH15 (modp3072), DH16 (modp4096), DH17 (modp6144), DH18 (modp8192), DH22 (modp1024s160), DH23 (modp2048s224), DH24 (modp2048s256), DH31 (curve25519)

PRF: PRF SHA-256, PRF SHA-384, PRF SHA-512

- Added a syslog option for VRRP State Changes notifications.
- A detailed log message will now be recorded when importing a configuration fails.
- Users can now select multiple inbound interfaces within the same group address for static multicast routes.
- Added support for DHCP error logs.
- Added support for the Modbus protocol to the Advanced Protection function in the CLI.
- Added support for RFC 5424 format for syslog messages.
- Added support for Default Action Log to the Layer 3-7 Policy function.

Bugs Fixed

- The maximum supported number of tunnels shown at the bottom of the IPsec Settings page is incorrect.
- The "Login Authentication Failure Message" does not save properly.
- Using the newline character (\n) in the 'Login Message' and 'Login Authentication Failure Message' causes abnormalities in the output.
- The system is unable to ping the VRRP virtual IP.
- Users are able to bypass password policy violation warnings by pressing ESC on the keyboard.
- Time zone settings are not saved if GMT is set to 0.
- The device randomly reboots several times after powering on.
- CVE-2024-6387 vulnerability issue. For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-246387.
- CVE-2024-9137, CVE-2024-9139 vulnerability issues. For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-241154.
- CVE-2024-1086 vulnerability issue. For more details, search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-249807.

Changes



- Changed the Trusted Access behavior: Trusted Access now applies to the Web UI, CLI, and New Moxa Command interfaces.
- Changed the Preempt Delay range for the VRRP function from 10 to 300 to 0 to 300.
- Changed the maximum password and share key length to 64 characters.
- The password and shared key now support special characters.

Notes

N/A

| | |
|-----------------------------------|------------------------|
| Version: v3.9.0 | Build: 24060420 |
| Release Date: Jun 04, 2024 | |

Applicable Products

OnCell G4302-LTE4 Series

Supported Operating Systems

N/A

New Features

- Added support for TACACS+ authentication.
- Added support for LAN ID to DHCP Option 82 in the DHCP relay agent.
- Added support for Proxy ARP for LAN interfaces.
- Added support for MRC Quick Link Ultra v4.0.0.
- Added support for Deep Packet Inspection (DPI).

Enhancements

- Increased maximum number of static multicast entries from 256 to 1000.
- Increased the maximum username length to 32 characters for local account, SNMP, RADIUS, and IEEE 802.1X authentication.
- Increased the maximum length of passwords, communities, and shared keys to 64 characters for local account, SNMP, RADIUS, and IEEE 802.1X authentication.
- Unified the range of supported special characters for local account, SNMP, RADIUS, and IEEE 802.1X.
- Modified the DoS policy for Flood Protection to allow independent limit ranges for each interface.
- Increased the maximum number of static multicast entries from 256 to 1000.
- Increased the maximum username length to 32 characters for local accounts, SNMP, RADIUS, and IEEE 802.1X authentication.
- Increased the maximum length of passwords, communities, and shared keys to 64 characters for local accounts, SNMP, RADIUS, and IEEE 802.1X authentication.
- Unified the range of supported special characters for local accounts, SNMP, RADIUS, and IEEE 802.1X.
- Modified the DoS policy for Flood Protection to allow independent limit ranges for each interface.

Bugs Fixed

- Users are unable to access the web console if their login password includes " \$\$".
- Units are incorrectly displaying as "packets" on the vertical axis of network statistics.
- Network statistics values are inaccurate when using ports for measurement.
- Restoring the device configuration may fail under specific circumstances.
- The allowed characters for the Password Policy are shown incorrectly.

Changes

N/A

Notes

N/A



| | |
|-----------------------------------|------------------------|
| Version: v3.0.0 | Build: 23082321 |
| Release Date: Aug 31, 2023 | |

Applicable Products

OnCell G4302-LTE4 Series

Supported Operating Systems

N/A

New Features

- Added support for the MXsecurity Series management software v1.1.0 through MXsecurity Agent Package v2.0.13.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A