MOXA®   Software Release Note

Software Name: IKS-G6524 & ICS-G7526/G7528 Series Firmware

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
3.5	Build_15030214	N/A	ICS-G7526 ICS-G7528 IKK-G6524	N/A	N/A	1. Support 64-bit packet counter	1. Randomly fail to save configuration file to ABC-01 2. Fail to import configuration file with specific parameter errors	
3.4	Build_14122516	N/A	ICS-G7526 ICS-G7528 IKK-G6524	N/A	N/A	N/A	1. ABC-01 connectivity Issue	
3.3	N/A	N/A	ICS-G7526 ICS-G7528 IKK-G6524	N/A	N/A	1. Add web interface for loop-protection enable/disable 2. Add web interface for SSH/SSL key generation 3. Add web interface/CLI/SNMP for NTP/SNTP client settings 4. Add SNMP MIB for SFP DDM (Diagnostics) 5. Support SFP-1GTXRJ45 10/100/1000 auto-negotiation	1. Login fail in CLI mode when password is with special character 2. Login authentication failed if the radius server does not support privilege levels assignment 3. IEEE 1588 PTP cannot function correctly 4. SFP DDM (Diagnostics) display inaccurate values 5. Configuration import/export fail after firmware upgrade 6. Restricts configuration import if the system name is too long 7. Hybrid VLAN lacks of SNMP MIB object	N/A
3.1	N/A	N/A	ICS-G7526 ICS-G7528 IKK-G6524	N/A	N/A	1. Pass ODVA EtherNet/IP certificate 2. Add some minor SNMP OIDs 3. Enhance multicast performance 4. Add version number in MIB file	1. NTP cannot synchronize time in default setting 2. NTP client function cannot work with Windows XP NTP server 3. Firmware Upgrade Failed when IEEE 802.1x is enabled 4. Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7)	N/A
1.0	N/A	N/A	ICS-G7526 ICS-G7528 IKK-G6524	1. Newly released for ICS-G7528/G7526 & IKS-G6524 series.	N/A	N/A	N/A	N/A