



Software Release Note

UC-8481-LX Series Firmware

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
1.0	Build_12042507	Linux	UC-8481-LX	First release.	N/A	N/A	N/A	N/A
1.1	Build_13062418	Linux	UC-8481-LX	N/A	1. Use new toolchain arm-linux_4.4.2-v4.1_Build_13031909.sh	1. Update pppd to v2.4.5	1. Fix occational failure in reset-to-default fuction 2. Fix Ready LED turn on/off fail issue 3. Modify the buzzer driver to generate louder sound	N/A