

Software Name: TAP-6226

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
1.6	Build 17090814	N/A	TAP-6226	<ol style="list-style-type: none"> [Web] Cookie is generated for each login. [Web] After sending out web page, web server only allows one person to send the data back to avoid CSRF (Cross-Site Request Forgery) Vulnerability. [Web] When changing password, alert user to use HTTPS. [Web] Encrypt the password, before transferring it. [Wireless Search Utility] Encrypt the data between the device and Wireless Search Utility. 	<ol style="list-style-type: none"> Removes the backdoor account. [Web] Login denied if device detect CSRF (Cross-Site Request Forgery) request. Change default password from "root" to "moxa". 	N/A	<ol style="list-style-type: none"> [Web] Fixes that some file/information can be gotten, even if user does not Login. [Web] Fixes that browser will re-direct to invalid web page, if the web page is tampered. [Web] Fixes that un-allowed Linux commands can be carried on the page input, and then the web server will execute them. [Web] Fixes that web server crash, if the URL is invalid [Web] Fixes that nonce are same in the same time produced. [Web] Fixes that cookie checks IP failed due to IP parsing in server is not correct 	N/A
1.5	Build 15050614	N/A	TAP-6226	N/A	<ol style="list-style-type: none"> Remove controller-based roaming tunnel_keep_alive mechanism 	N/A	<ol style="list-style-type: none"> Bugfix: MOXA Search Utility password mis-detection. Bugfix: LED not working properly in the event of IP conflict. Bugfix: NTP timezone offset problem Bugfix: Duplicate CCoA issue in interAC roaming Bugfix: Fix pure G data rate table Bugfix: Fix tv manage queue overload issue 	N/A
1.1	Build 14092419	N/A	TAP-6226	1. First release	N/A	N/A	N/A	N/A