



Firmware for NAT-102 Series Release Notes

Version: v3.19	Build: 25071510
Release Date: Jul 31, 2025	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added SMTPS support in email settings.

Enhancements

N/A

Bugs Fixed

- The local time does not change according to the selected time zone when Daylight Saving Time is enabled.
- State LED UI hint not accurate.
- Navigating to Syslog page causes unexpected sign out.
- Device stops responding to NTP requests from LAN clients.
- Certain characters in passwords cause sign in failures.
- Enabling or disabling a user account required re-entering the password modification.

Changes

N/A

Notes

N/A



Version: v3.17	Build: N/A
Release Date: Apr 01, 2025	

Applicable Products

NAT-102 Series

Supported Operating Systems

N/A

New Features

- Added Traceroute CLI command.
- Introduced multi-language support for MX-ROS, including Traditional/Simplified Chinese, Korean, and Japanese.

Enhancements

N/A

Bugs Fixed

N/A

Changes

- Supervisor and user accounts are no longer created by default, and must be added manually. Existing accounts are not affected.

Notes

- Before upgrading a NAT-100 Series device from v1.x to v3.17, we recommend saving a reference copy of the device's configuration to the local host and manually reconfiguring the device after upgrading to v3.17 to avoid compatibility issues.



Version: v3.15	Build: N/A
Release Date: Jan 09, 2025	

Applicable Products

NAT-102 Series

Supported Operating Systems

N/A

New Features

- Added support for the MX-ROS software platform.
- Added support for the MXview One management software. (Est. availability:Jan, 2025)
- Added support for the MXconfig software.
- Added support for SNMP, SNMP Trap/Inform V1, V2c, V3 functionality.
- Added support for NTP Authentication functionality.
- Added support for Setting Check functionality.
- Added the “Auto Create Source NAT” option to the NAT function.
- Added support for Certificate Management functionality.
- Added support for Login Authentication for Local, RADIUS, and TACACS+.
- Added support for MXview Alert Notification functionality.
- Added support for Network Statistics functionality.
- Added support for LLDP functionality.
- Added support for Syslog Authentication functionality.

Enhancements

- Added the TFTP, SCP, and SFTP methods for firmware upgrades.
- Added TFTP, SCP, and SFTP methods for configuration backup and restore.
- Users can now manually modify the Device Lockdown learning table and create list entries with user-specified interfaces.
- Added event notifications for the following events: Device Lockdown State Change, Firmware Upgrade Success, Firmware Upgrade Failure, Log Service Ready.
- Added the CPU Usage tab to Event Notification. This allows users to configure a CPU usage warning threshold.

Bugs Fixed

- CVE-2024-9138 CVE-2024-9140 vulnerability issues. For more details search the Security Advisories section on the Moxa website for the following Security Advisory ID: MPSA-241155

Changes

N/A

Notes

- Before upgrading a NAT-100 Series device from v1.x to v3.15, we recommend saving a reference copy of the device’s configuration to the local host and manually reconfiguring the device after upgrading to v3.15 to avoid compatibility issues.
- (Known issue) The Bandwidth Utilization widget in the Network Statistics screen displays incorrectly.



Version: v1.0.5	Build: 23073117
Release Date: Sep 11, 2023	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- IPV-230306
- The WAN interface loses its connection after a power cycle.
- Connecting the Ethernet port to another device may sometimes cause the link to go down.
- The netmask of the WAN interface is unintentionally changed after rebooting the device.

Changes

N/A

Notes

N/A



Version: v1.0.3	Build: 22102112
Release Date: Oct 28, 2022	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- The system will stop recording Syslog event logs if the device name contains "moxa".
- Users are unable to change the device password when logged in using the default username and password.

Changes

N/A

Notes

This is a beta firmware release for bug fixing only.



Version: v1.0.1	Build: 22033117
Release Date: Apr 06, 2022	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- An incorrect interface name (exceeding 12 characters) causes the NAT function to stop working.

Changes

N/A

Notes

Note: This is a minor firmware update to address the listed bug. If you do not wish to upgrade the NAT-102 firmware, you can also rename the interface to solve this issue.



Version: v1.0	Build: 21111216
Release Date: Dec 24, 2021	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A