



## Firmware for MGate 5111 Series Release Notes

<b>Version: v2.1</b>	<b>Build: 23090415</b>
<b>Release Date: Sep 26, 2023</b>	

### Applicable Products

MGate 5111 Series

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

- Upgrades OpenSSL version to v1.1.1t.
- Upgrades SQLite version to v3.41.2.
- Enhances the PROFINET DCP rate limit function when too many DCP discovery requests are received in a short time.
- Enhances the Modbus RTU/ASCII Traffic Monitor display mechanism.
- Enhances the protection of the MGate Modbus TCP server against flooding caused by excessive Modbus TCP connections and requests.

### Bugs Fixed

- Quick setup missed adding an I/O during the PROFIBUS slave step.
- An issue with the Modbus inter-character timer mechanism when receiving only one character.
- Web UI freezes when the DNS server does not respond.

### Changes

N/A

### Notes

N/A



<b>Version: v2.0</b>	<b>Build: 22041811</b>
<b>Release Date: May 31, 2023</b>	

### **Applicable Products**

MGate 5111 Series

### **Supported Operating Systems**

N/A

### **New Features**

- Supports new product version V1.1.0

### **Enhancements**

- Upgraded OpenSSL version to v1.1.1l
- Upgraded Dropbear version to 2020.81
- Upgraded Net-SNMP version to v5.9.1
- Supports the HTTP response headers (HSTS, X-Frame-Option, X-Content-Type-Options) for security purposes.
- Provides the optional configuration feature of "Accept Arbitrary Host Header"

### **Bugs Fixed**

- Fixed the Modbus server function, which stopped when the system IP address changed.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.4</b>	<b>Build: 22032313</b>
<b>Release Date: Apr 29, 2022</b>	

### **Applicable Products**

MGate 5111 Series

### **Supported Operating Systems**

N/A

### **New Features**

- Supports the HTTP response headers (HSTS, X-Frame-Option, X-Content-Type-Options) for security purposes.

### **Enhancements**

- Upgraded the OpenSSL version to v1.1.1l
- Upgraded the Dropbear version to 2020.81
- Upgraded the Net-SNMP version to v5.9.1

### **Bugs Fixed**

- Fixed the Modbus server function, which stopped when the system IP address changed.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.3</b>	<b>Build: Build 21020513</b>
<b>Release Date: Mar 02, 2021</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

- Supports MCC Tool.

### **Enhancements**

- Supports MXconfig v2.6 and MXview v3.2.
- Enhanced log table placement.
- Enhanced cipher suite.
- Upgraded SQLite version to v3.33.0.

### **Bugs Fixed**

- Fixed the stuck system issue when the IP setting begins with a zero digit.
- Fixed the command injection cybersecurity vulnerability with a built-in web console UI.
- Fixed CVE-2019-11477.
- Fixed CVE-2011-1473.
- Fixed the memory leak when receiving the wrong LLDP packets continuously.

### **Changes**

- The default setting for the telnet console has been disabled.
- Extended the length of the email alert username.
- Changed the default TCP/IP keep alive check timeout to 1 minute.

### **Notes**

N/A



<b>Version: v1.2</b>	<b>Build: Build 19052811</b>
<b>Release Date: Jul 02, 2019</b>	

### **Applicable Products**

MGate 5111, MGate 5111-T

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

- Upgraded OpenSSL version to v1.1.1b.
- Upgraded SQLite version to v3.27.2.
- Upgraded Net-SNMP version to v5.7.3.
- Optimized the response time on Modbus write command under Modbus slave mode.
- Optimized PROFIBUS slave data exchange performance.

### **Bugs Fixed**

N/A

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.1</b>	<b>Build: Build 18012622</b>
<b>Release Date: Mar 02, 2018</b>	

### **Applicable Products**

MGate 5111, MGate 5111-T

### **Supported Operating Systems**

N/A

### **New Features**

- Passed PI (PROFIBUS & PROFINET International) PROFIBUS Slave certification test.

### **Enhancements**

N/A

### **Bugs Fixed**

- According to EtherNet/IP Specification (CT14), aligned Manual Setting attribute of Ethernet Link Object with the identically-named bit in the Interface Capability attribute.
- Fixed incorrect topology display due to forwarding LLDP frames to another LAN port.

### **Changes**

N/A

### **Notes**

N/A



<b>Version: v1.0</b>	<b>Build: Build 17110222</b>
<b>Release Date: Jan 19, 2018</b>	

**Applicable Products**

MGate 5111, MGate 5111-T

**Supported Operating Systems**

N/A

**New Features**

- First release.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A